

Fig.1




Fig.2




FIG. 1

2/15




Fig. 3a




Fig. 3b

Fig. 4





Fig. 5



09831364-022901

3/15







Fig. 8

Fig. 9

00831364-082890

4/15

Fig.10




Fig.11





Fig.12



5/15

Fig.13




Fig.14





Fig.15



106280" 49E1E860

6/15

Fig.16




Fig.17




Fig.18





Fig.19



0931364-082901

WO 00/31758

PCT/FR99/02771

7/15




Fig. 20




Fig. 21




Fig. 22




Fig. 23

0981364-08201

8/15




Fig. 24




Fig. 25




Fig. 26

09831364-082901



WO 00/31758

9/15







FIG. 27a

WO 00/31758

10/15

Fig.30




Fig.31





Fig.32



106280-49E1E860

WO 00/31758

11/15




Fig. 33




Fig. 34

09831364 19990401

12/15





Fig.36



09/831364 052901 105230 " 1987E360

WO 00/31758

13/15




Fig. 40




Fig. 41





Fig. 42



09831364-002901

WO 00/31758

14/15

Fig.37





Fig.38



09831364-022901

15/15

Fig.44




Fig.43

